
An Overview of Dakota Access Pipeline Issues: A North Dakota Perspective

Jennifer L. Verleger, P.E., Assistant Attorney General, ND Attorney General's Office



Project Background



- Built By Dakota Access, LLC (Owned By Energy Transfer Partners, LP)
- 1,172-Mile Underground Pipeline
- Begins Near Stanley, ND & Ends In Patoka, IL
- Will Transport Light, Sweet Crude Oil From The Bakken To Market

Approving Agencies

- The Dakota Access Pipeline Was Approved By:
 - South Dakota Public Utilities Commission
 - North Dakota Public Service Commission
 - Iowa Utilities Board
 - Illinois Commerce Commission
 - U.S. Army Corps Of Engineers

Issues Pertaining to Water

- River Crossing Required A Sovereign Lands Permit (North Dakota Office Of The State Engineer)
 - Primary Concerns Were Allowing Vertical & Horizontal Movement Of Water Without Compromising The Pipe; &
 - Utilization Of The Most Modern, State-Of-The-Art Safety Features & Equipment
 - All Concerns Were Met By The Applicant


Issues Pertaining to Water

- Scour Analysis Required By SWC
 - Current Minimum Federal Standards Require Only 4 Feet "Depth Of Cover"
 - Source: 49CFR Part 195, Subpart D: Cover Over Buried Pipeline
 - OSE Contracted HDR To Review DAPL's Scour Analysis, Which Found:
 - 20 Feet Of Potential Scour At Lake Oahe Crossing Location
 - Therefore, OSE Required "Total Scour Plus 4 Feet" (20'+4'=24' Minimum Depth)
 - DAPL's Actual Depth Is A Minimum Of 95 Feet

Issues Pertaining to Water


- Groundwater Considerations
 - The Material Below Lake Oahe Is In Connection With The Hydraulics Of The River
 - If DAPL Were Not Deep Enough, The Nature Of The Deposits Would Allow A Potential Pipeline Breach To Contaminate Both The Aquifer & The River
 - Drilling 95 Feet Below The Lake Bed Alleviated These Concerns

Crossing Lake Oahe



DAPL Is A Minimum Of 95 Feet Below The Lake Bed

Lake Oahe Continued



- Crosses Lake Oahe In Morton & Emmons County, ND On Privately Owned Land
- North Of The Standing Rock Sioux Reservation (Sioux County, ND)

Standing Rock Tribe's Water Intake



- Currently, The Tribe's Water Intake Is Located In Fort Yates, ND, On Tribal Land
- By The End Of 2017, The Intake Is Scheduled To Be Moved Approximately 50 Miles South, Near Mobridge, SD

Protest Activity Begins

August 2016: Protesters Began Gathering In Morton County In Opposition Of DAPL

Construction Law Enforcen Activity

Protest Activity Intensifies

Protesters Began Securing Themselves To Equipment With Devices Called "Sleeping



Protest Activity Intensifies


Law Enforcement & DAPL Equipment Were Targets Of The



Social Media


The State Was III-Prepared To Counteract The Protestors' Use Of Powerful Images On Social Media





Social Media

The "NoDAPL" Cause Raised Millions Of Dollars Via Donations Using Social Media



Social Media

Anti-Law Enforcement Images Shaped What Became An International Narrative



Social Media Efforts

State & Local Government Begin To Counteract Protest Social Media Efforts

- Know The Truth Campaign Begins
 - ND Response Website Developed
 - Press Releases Made Easily Accessible By State And Local Entities
 - "By The Numbers" And Daily Activity Statistics Published On A Regular Basis
 - "Myth Vs Fact" Publications Released To The Public To Clarify News Headlines

Location of Protest Camps

- The Majority Of The Most Active Protest Camps Were Located On US Army Corps Of Engineers (USACE) Land
 - State & Local Leadership Continually Asked USACE To Act; The Requests Were Met With Little To No Response, Despite USACE's Approval Of The Overall Project

Location of Protest Camps




Potential Flooding



Potential Flooding



Winter Storms



21



Severe Storms In November & December Delivered Record High Levels Of Precipitation

- These Storms Brought About Dangerous Travel Conditions & Deadly Wind-Chills;
- The New Snow Pack Magnified Pre-Existing Concerns Of Potential Spring Flooding

 NDResponse

Camp Clean-Up



February 23rd, 2017:

- Representatives From USACE Met With Protesters To Discuss Priorities Of Cleaning Up The Camps To Their Pre-Protest Condition
- Law Enforcement Officers
 Proceeded To Move
 Through The Camp & At
 2:09 PM, The Camp Was
 Declared Clear & Secure

Camp Clean-Up Statistics



7 days into cleanup and so far 418,000 pounds of garbage has been removed from #DAPL protest camp. ow.ly/



bV9h308Jyaa

- \$1.1 Million Clean-Up Cost
- 835 Roll-Off Dumpsters Full Of Trash
- 44 Total Vehicles Abandoned
- 12 Dogs Rescued & Brought To Shelters

DAPL By the Numbers



A snapshot of resources diverted from normal operations to support state and local response to protest events and related illegal activity in Morton County and the Bismarck/Mandan region since August 10, 2016, ensuring public safety and law and order.



210 days



\$30 million



\$4.1 million



\$4.1 million equipment/supplies

equipment/supplies (cold weather gear, radios, fuel)



\$38.2 million

total state and local costs to taxpayers (estimated as of March 6, 2017)

106

In state agencies providing support

10

States providing support¹

34

Out of state agencies providing support

761

Number of arrests

709

Number of protesters arrested

94%

Arrestees from out of state

227

Number of arrestees with prior criminal records²

- Alabama, Indiana, Louisiana, Minnesota, Montana, Nebraska, Ohio, South Dakota, Wisconsin, Wyoming
- Total of 1.503 previous citations and charges for illegal activity (as of March 1. 2017)

Sources: North Dakota Department of Emergency Services, Morton County Sheriff's Department

NDResponse

Questions?



THANK YOU

For More Information www.NDResponse.gov

Jennifer L. Verleger, P.E.

Assistant Attorney General

ND Attorney General's Office

Phone: 328-3537

Email: jverleger@nd.gov